

বাংলাদেশপেট্রোলিয়ামএক্সপ্লোরেশনএন্ডপ্রোডাকশনকোম্পানীলিমিটেড (বাপেক্স)



Bangladesh Petroleum Exploration and Production Company Limited (BAPEX)
Foreign Purchase Department, Administration Division
Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215, Bangladesh
web: www.bapex.com.bd

Ref: 28.09.0000.150.41.001.23(1213)

Re-Invitation of Expression of Interest (Re-EOI)

Date:12-11-2023

1	Ministry/Division	Ministry of Power, Energy & Mineral Resources/Energy & Mineral Resources Division
2	Agency	BangladeshOil, Gas and Mineral Corporation (Petrobangla)
3	Procuring Entity Name	Bangladesh Petroleum Exploration & Production Co. Ltd., (BAPEX)
4	Procuring Entity District	Dhaka
5	Expression of interest (EOI)	Selection of Consulting Firm (International) for One Top Drive Service Engineer
6	EOI No. and Date	BAPEX/ADMIN/INT/EOI-1213/2023, Date: 12-11-2023
Key	Information	
7	Procurement Method	Quality and Cost Based Selection (QCBS)
	iding Information	
8	Budget and Source of Funds	BAPEX own Fund
	ticular Information	
9	Indenting Division/Project	Engineering Division/KTL-8 Drilling Project
10	EOI Closing Date & Time	07-12-2023 at 11.00 Hrs. (BST)
11	Brief Description of Assignment	Top Drive:
		Model: 1250AC-681, Serial No.: 1161,
		Manufacturer: CANRIG Drilling Technology Ltd, USA. Objectives:
		BAPEX looking for qualified Companies interested to provide CANRIG Top Drive Service Engineer.
		The scope of work for service engineer includes but is not limited to as under:
		a) Perform maintenance and repair job on specified Top Drive and report tothe field engineer.
		b) Perform Fault finding, troubleshooting and diagnose of VFD & PLC System of Top Drive system as
		required for smooth drilling operation.
		c) Shall provide for preventive, routine and non-routine maintenance and forthe repair of PLC. VFD, industrial
		Communication, Hydraulic System and related equipment of the Top Drive.
		d) Supervise the Electrical System, Mechanical System, and Communication System. Hydraulic System and
		related peripherals of the top drive during drilling. Ifneeded replace devices as per condition and
		recommendation.
		e) The Service Engineer should bring one laptop with adequate Software, PLC to PC communication cable,
		Inverter to PC communication cable andother related accessories as required to repair, maintenance and programming of PLC & VFD System of Canrig Top Drive of Model-1250AC-681, Serial No: 1161.
		f) Check the present stock of spare parts and consumables & Make a reliable list of spare parts and
		consumables.
		g) During service period, the professional will stay in well site 24 hour and train up the BAPEX Engineers.
12	Location of the Project	Sylhet District, Bangladesh
13	Procuring Entity Details	General Manager, Administration Division, Phone: +880-255011774,
		Email: purchase.bapex@gmail.com
14	Address of the Official Inviting	General Manager (Administration), BAPEX Bhaban (Level-5), 4 Kawran Bazar C/A, Dhaka
		General Manager (Administration), BAPEA Briadan (Level-5), 4 Kawran Bazar C/A, Dhaka
	Tender	General Manager (Administration), BAPEA Briadan (Level-5), 4 Kawran Bazar C/A, Dhaka
15	Experience, Resources &	-Top Drive Service Engineer:
15		-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance.
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system.
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
15	Experience, Resources &	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
	Experience, Resources & Delivery Capacity Required	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
16	Experience, Resources & Delivery Capacity Required Place of Submission	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215.
	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
16	Experience, Resources & Delivery Capacity Required Place of Submission	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider:
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering.
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	 -Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Proflbus. Modbus. DeviceNet. Control
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Profibus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System.
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Proflbus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing.
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Proflbus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Profibus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project.
16	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD systemService Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Proflbus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project. e) Authorization letter from CANRIG Drilling Technology Ltd.
16 17	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service Provider & Top drive engineer	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Profibus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project.
16 17	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service Provider & Top drive engineer	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD systemService Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Profibus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project. e) Authorization letter from CANRIG Drilling Technology Ltd. f) Strong Administrative and Financial capacity to carry out the project.
16 17	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service Provider & Top drive engineer mation for Tenderer This Tender Notice will also be ava	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD system. -Service Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Proflbus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project. e) Authorization letter from CANRIG Drilling Technology Ltd. f) Strong Administrative and Financial capacity to carry out the project.
16 17	Experience, Resources & Delivery Capacity Required Place of Submission Eligibility of the Service Provider & Top drive engineer mation for Tenderer This Tender Notice will also be ava This Tender will be conducted as pe	-Top Drive Service Engineer: a) At least 5 years of prior work experience in Canrig VFD Top Drive servicing and maintenance. b) Shall be capable of Faults findings, Troubleshooting, Repairing, Servicing and programming of PLC and VFD systemService Provider: a) The participants must have experience on providing Engineering Services. The participants should submit the evidence of experience with his offer. b) The service provider should provide at least 3 (three) Curriculum Vitae for Top Drive Service Engineers. All are must be employees of CANRIG Drilling Technology Ltd., USA and currently working on CANRIG Top Drive. c) The Service Provider should be committed and prompt to provide Engineering Services in Time. They have to coordinate and cooperate with BAPEX for smooth Service. Foreign Purchase Department, Level-4, BAPEX Bhaban, 4 Kawran Bazar C/A, Dhaka-1215. The BAPEX invites this Expression of Interest (EOI) from all eligible service providers to provide Top Drive Engineering Services. The Service Provider must have: a) The Service Engineer must have Minimum of a Bachelor's degree in engineering. b) Demonstrated knowledge and experience in PLC, VFD, EtherNet/IP, Profibus. Modbus. DeviceNet. Control Net Network Communication and Hydraulic System. c) The Professionals should be capable of English speaking and writing. d) The Service Provider shall have authorization letter from CANRIG Drilling Technology Ltd. to prove they are authentic & capable to carry out the project. e) Authorization letter from CANRIG Drilling Technology Ltd. f) Strong Administrative and Financial capacity to carry out the project.

General Manager (Admin)

Administration Division